ASBESTOS INSPECTION REPORT FOR TAYLOR HALL



TAYLOR HALL

Montana State University Bozeman, Montana

Report Requested By:

MONTANA STATE UNIVERSITY
Facilities Services

Prepared By:



DATE OF INSPECTION: 04/23/13

REVISED ON 12/18/13

Table of Contents

Introduction	3
Inspection Procedures	3
Inspection Summary Table	5
Disclaimer	8
Appendix A – Photographs of Samples	9
Appendix B – Sample Analysis Report by EMSL Raleigh, NC Laboratory	13
Appendix C – Chain of Custody Documents	28
Appendix D – Floor Plans	32
Appendix E – Acronyms & Abbreviations	38

Credentials

Authored By:		
	Sonia Rogers, IH	
Reviewed By:		
	Scott Rogers CIH CHMM	

Asbestos Certifications:

Name	MTA#	Inspector	Contractor / Supervisor	Project Designer	Management Planner
Scott Rogers, CIH CSP CHMM	2322	10/31/2013	11/02/2013	11/01/2013	10/31/2013
Sonia Rogers, IH	3150	10/31/2013	11/02/2013	11/01/2013	
Darrell Freeland	3892	03/13/2014	03/12/2014		

INTRODUCTION

Sonia Rogers, Scott Rogers and Darrell Freeland, of Environmental Solutions LLC performed a comprehensive full building asbestos inspection on April 23, 2013, of Taylor Hall located on the campus of Montana State University in Bozeman, Montana. This evaluation was performed at the request of Montana State University Facilities Services Division.

Taylor Hall consists of and original three story building with a full basement built in 1894, and a single story annex to the east. The main building is a brick building on a rock foundation with a vaulted wood shake roof. The annex section of the building is also a brick and concrete structure with a flat built up roof. Taylor Hall is the oldest building on campus and has undergone multiple renovations over the years. The facility is currently home to the 4-H Foundation and Extension Services.

The intent of this report is to properly identify the presence of asbestos containing materials that will be impacted during an upcoming renovation project. This report and its recommendations are pursuant to the NESHAP requirements (40 CFR 61.145) and the Administrative Rules of Montana (17.74.307) as administered by the Montana Department of Environmental Quality, Asbestos Control Program.

The regulations require the building owner to have the facility inspected for the presence of asbestos containing material(s) (ACM) prior to the construction, renovation or demolition of the facility. The owner is required to provide information obtained from the inspection to those who may be impacted such as, but not limited to, contractors, sub-contractors and/or employees. ARM 17.74.307 requires that the inspection be conducted by a Montana Accredited Inspector.

INSPECTION PROCEDURES

The inspection was conducted by our accredited inspectors, Sonia Rogers, Scott Rogers and Darrell Freeland, and consisted of a detailed visual survey of the building. Following a brief review of the facility inspectors entered the building with sampling equipment and began to assess the homogenous areas. Suspect ACBM was then grouped into homogenous materials and a sampling plan was developed.

Inspectors determined that 25 homogeneous materials were present and collected 72 representative samples from these materials. Five (5) of the 25 materials were found to contain asbestos quantities greater than 1% (9x9 & 12x12 Floor Tiles, Linoleum, Exterior Window Caulk and Roofing Tars). One (1) material was found to contain asbestos quantities of a trace or less than 1% (Drywall Mud). One (1) material was assumed to contain quantities greater than 1% (Stainless Steel Sink Insulation). See the Inspection Summary for a more detailed description and location of materials sampled.

Materials were collected wet to avoid dust generation and placed into Ziploc bags for transport. The materials were submitted to EMSL Laboratories, Raleigh, North Carolina. EMSL is an "accredited" laboratory under the National Voluntary Laboratory Accreditation Program (NVLAP), Laboratory Code #200671-0, which employs Polarized Light Microscopic (PLM) techniques with dispersion staining for identification of mineral forms of asbestos. The quantification of asbestos in the sample is intended to be an estimate only and the limit of detection for this method is approximately 1% by volume.

Bulk samples obtained during the inspection were assigned bulk sample numbers and entered on the sample summary / chain of custody forms. The samples were transported to the laboratory via Fed-Ex (Standard Overnight).

Sample locations for this survey were chosen in a random fashion, with emphasis placed on obtaining samples of each type of accessible, suspect material and minimizing damage to the material being sampled. Samples were collected by carefully removing small portions of the suspect material in a non-invasive manner, when possible. If possible, samples from existing damaged areas or loose pieces of material were collected.

The intent of the inspection was to identify the suspect materials, assume that materials contain asbestos or collect samples of materials to determine if they are ACM and assess the friability of the materials. Materials that were assumed to contain asbestos or that were identified as containing greater than 1% asbestos were categorized as a regulated asbestos containing material (RACM), Category I Non-Friable ACM, Category I RACM or Category II Non-Friable ACM based on the type and the condition of the material.

<u>Sample analysis results are included in Appendix B and Chain of Custody documents are included in Appendix C</u>.

ENVIRONMENTAL SOLUTIONS INSPECTION SUMMARY

SAMPLE ID	SAMPLE DESCRIPTION	SAMPLE COLOR	APPROX SQ/FT	MATERIAL DESIGNATION	LAB RESULTS	MATERIAL LOCATIONS	RECOMMENDATIONS
01, 02, 03	Plaster	White/Gray	N/A	N/A	None Detected	Interior Walls	N/A
04, 05, 06	Rock Pointing (Mortar)	Gray	N/A	N/A	None Detected	Basement Foundation	N/A
07, 08, 09	Concrete	Gray	N/A	N/A	None Detected	Basement Floors & Foundation	N/A
10, 11, 12	Window Glazing (Between Glass & Wood)	Gray/White	N/A	N/A	None Detected	Basement Wood Windows	N/A
13, 14, 15	4" Rubber Base w/Glue	Black	N/A	N/A	None Detected	Basement	N/A
16, 17, 18	Mastic	Black	N/A	N/A	None Detected	Basement Concrete Floors	N/A
19, 20, 21	Paint	White	N/A	N/A	None Detected	Basement Walls	N/A
22, 23, 24	Drywall/Mud/Texture	White	N/A	N/A	None Detected	Basement Walls	N/A
25, 26, 27	12x12 Floor Tile w/Mastic	Dark Gray w/Gray Specs	N/A	N/A	None Detected	Area 013 Landing	N/A
28, 29, 30	CMU	Gray	N/A	N/A	None Detected	Basement	N/A
31, 32, 33	CMU Mortar	Gray	N/A	N/A	None Detected	Basement	N/A
34, 35, 36	12x12 Floor Tile w/Mastic	Cream w/Brown Stripes	35	Category I Non-Friable	Tile=2% Chrysotile Mastic=None Detected	1 st Floor Restroom (#110)	Renovation that requires the impact and/or removal of the floor tile must include the abatement of the material and must be performed by a Montana accredited asbestos abatement contractor according to local, state, and federal regulations.
37, 38, 39	4" Rubber Base	Black	N/A	N/A	None Detected	1 st Floor	N/A
40, 41, 42	2x4 Ceiling Tiles (Waves / Multi Pin Holes)	White/Gray	N/A	N/A	None Detected	1 st Floor	N/A
43, 44, 45	12x12 Ceiling Tiles	White/Wood	N/A	N/A	None Detected	2 nd Floor	N/A
46, 47, 48	12x12 Ceiling Tile Glue	Dark Brown	N/A	N/A	None Detected	2 nd Floor	N/A

Environmental Solutions LLC Page 5

ENVIRONMENTAL SOLUTIONS INSPECTION SUMMARY

	APPROX MATERIAL									
SAMPLE ID	SAMPLE DESCRIPTION	SAMPLE COLOR	SQ/FT	DESIGNATION	LAB RESULTS	MATERIAL LOCATIONS	RECOMMENDATIONS			
49, 50, 51	Linoleum w/Glue	Tan (Stone Pattern)	35	Category I Non-Friable	Lino = 25% Chrysotile Glue=<1% Chrysotile	2 nd Floor Restroom (#212)	Renovation that requires the impact and/or removal of the linoleum and glue must include the abatement of the materials and must be performed by a Montana accredited asbestos abatement contractor according to local, state, and federal regulations.			
52, 53, 54	9x9 Floor Tile w/Mastic	Light Blue/Cream & Tan	1,180	Category I Non-Friable	Tile = 2% Chrysotile Mastic=Non Detected	Rooms: 213, 300, 301, 302, 303, 304, 305	Renovation that requires the impact and/or removal of the floor tile must include the abatement of the material and must be performed by a Montana accredited asbestos abatement contractor according to local, state, and federal regulations.			
55, 56, 57	Drywall/Mud/Texture	White w/Paint	N/A	N/A	Drywall = None Detected Mud = 5% Chrysotile Composite=<1% 400 Point Ct=<0.25% Chrysotile	2 nd & 3 rd Floors	Impact of this material is not regulated by the EPA and DEQ as an asbestos containing material; however, OSHA guidelines must be followed for workers. Verification of <1% PLM result performed by required 400-Point Count Method.			
58, 59, 60	Wall Tile Glue	Dark Brown	N/A	N/A	None Detected	Room 303	N/A			
61, 62, 63	Brick	Red	N/A	N/A	None Detected	Exterior	N/A			
64, 65, 66	Brick Mortar	Gray	N/A	N/A	None Detected	Exterior	N/A			
67, 68, 69	Exterior Window Caulk (Between Window & Building)	White	41 Windows	Category I Non-Friable	2-3% Chrysotile	Exterior Windows	Renovation that requires the impact and/or removal of the floor tile must include the abatement of the material and must be performed by a Montana accredited asbestos abatement contractor according to local, state, and federal regulations.			
70, 71, 72	Roofing Tars (3 Layers)	Black/Silver	1,000	Category I Non-Friable	2-8% Chrysotile	Flat Roofs (East Annex & North Entry Roof)	Impact of this asbestos containing material is regulated by both environmental and worker protection regulations. Asbestos accredited persons must perform all work impacting, disturbing, or requiring the removal of this material following regulatory requirements.			

Environmental Solutions LLC Page 6

ENVIRONMENTAL SOLUTIONS INSPECTION SUMMARY

IMENDATIONS	RECOMMENDATION	MATERIAL LOCATIONS	LAB RESULTS	MATERIAL DESIGNATION	APPROX SQ/FT	SAMPLE COLOR	SAMPLE DESCRIPTION	SAMPLE ID
olition and disposed of as ning waste. Work to be a Montana Accredited ractor according to local,	Sinks must be removed prenovation/demolition and disastestos containing waste. Vertically a Montana A Abatement Contractor according state, and federal regular	Rooms: 003, 300	Assumed	Category II Non-Friable	2	Black	Stainless Steel Sink Insulation	N/A
							Samples 12/18/13	Additional S
N/A	N/A	Under 9x9 Floor Tile on 3 rd Floor (300, 301, 302, 303, 304, 305)	None Detected	N/A	N/A	Black	Tar Paper	01, 02, 03
						% Asbestos	Materials containing >1	
				otoo	unto of Aobo	taining Traca Amai	Materials of Note Co.	
	,	3 rd Floor (300, 301, 302,	None Detected	·	· ·	% Asbestos	Tar Paper	

ENVIRONMENTAL SOLUTIONS INSPECTION SUMMARY FOR CHEEVER HALL

9x9 Floor Tile w/Mastic Locations and Sq/ft Numbers: Tiles are located in the following areas (213, 300, 301, 302, 303, 304, and 305). There is approximately 1,180 sq/ft of 9x9 floor tile (2nd Floor = 35, 3rd Floor=1,145).

Window NOTE: Exterior window caulk located between the wood frame and building contains a regulated quantity of asbestos. Total of 41 window openings that contain these types of windows.

TSI Fittings NOTE: No visible TSI was located in the building; all exposed pipe insulation is fiberglass. However, it is our opinion that additional TSI fittings are located in vertical pipe chases and buried in the walls. All TSI fittings are assumed to contain regulated quantities of asbestos. Care should be taken when opening any enclosed spaces.

Roofing Materials NOTE: The main building has a wood shake roof. The old wood roof was completely removed and replaced with new wood shakes during the summer of 2012. The East Annex Roof and the North Main Entry Flat roofs are a rolled tar/asphalt and are positive for regulated quantities of asbestos. All layers of both of these roofs should be treated as asbestos containing and disposed of as asbestos waste. In the present condition the materials are Non-Friable; however materials may become friable during a demolition/renovation project. Removal work practice shall be reviewed by a licensed and Montana accredited Asbestos Inspector for final determination on condition of materials.

Areas of Limited or No Access:

- Vertical pipe chases behind walls (limited access). All visible pipe chases contained straight runs of fiberglass insulation.
- Electrical Vault Area.

Environmental Solutions LLC Page 7

DISCLAIMERS

This document and its contents incorporated herein, is proprietary information and as an instrument of professional services, is the property of Environmental Solutions LLC, and are not to be used, in part or in whole for any other project without the written authorization of Environmental Solutions LLC.

This asbestos assessment report was prepared based on information obtained during the surveys, interpretation of the laboratory results of bulk samples of building materials collected during the surveys. The conclusions of this report are professional opinions based solely upon visual site observations and interpretations of laboratory analysis and field data as described in our report.

This report has been prepared to provide information concerning the various types and estimated quantities of asbestos-containing materials that may be impacted during this project. While extreme effort was made to inspect every aspect of the buildings, it still includes only those materials that were visible and accessible at the time of our inspection.

Our opinions are intended exclusively for use by Montana State University. The scope of services performed by Environmental Solutions LLC may not be appropriate to satisfy the needs of other users, and any use or re-use of this document, or the findings presented herein, is at the sole risk of the user.

The opinions presented herein apply to the site conditions existing at the time of our investigation. Therefore, our opinions and recommendations may not apply to future conditions that may exist at the site, which we have not had the opportunity to evaluate.

PHOTOGRAPHS SAMPLES



Plaster



Foundation Rock Pointing (Mortar)



Concrete



Window Glazing



4" Rubber Base w/Glue



Mastic

PHOTOGRAPHS OF SAMPLES CONTINUED



Paint (Surfacing Material)




Drywall / Mud / Texture



12x12 Floor Tile w/Mastic (Dark Gray)



CMU & CMU Mortar



12x12 Floor Tile w/Mastic (Cream)



4" Rubber Base w/Glue

PHOTOGRAPHS OF SAMPLES CONTINUED



2x4 Ceiling Tiles



12x12 Ceiling Tiles



12x12 Ceiling Tile Glue



Linoleum w/Glue (Tan Stone Pattern)




9x9 Floor Tile w/Mastic




Drywall / Mud / Texture

PHOTOGRAPHS OF SAMPLES CONTINUED



Wall Tile Glue (Room w/Ceiling Tiles on Walls)



Brick & Brick Mortar



Exterior Window Caulk



Roofing Tars (3 Layers)



Stainless Steel Sink Insulation

APPENDIX B

Sample Analysis Report by EMSL Raleigh, NC Laboratory



2500 Gateway Centre Blvd., Suite 600, Morrisville, NC 27560

Phone/Fax: (919) 465-3900 / (919) 465-3950

http://www.emsl.com raleighlab@emsl.com

EMSL Order: 29° CustomerID: EN

291302415 ENSO62

CustomerPO:

ProjectID:

Attn: Sonia Rogers

Environmental Solutions, LLC

PO Box 7010

Phone: Fax:

(406) 579-1441

Received:

05/02/13 9:30 AM

Analysis Date: 5/7/2013

Collected:

Bozeman, MT 59771

Project: 13031-01, Taylor Hall

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

			Non-Ask	<u>oestos</u>	<u>Asbestos</u>	
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type	
01	Plaster	Gray/White	5% Cellulose	89% Non-fibrous (other)	None Detected	
291302415-0001		Fibrous	3% Synthetic			
20.002.10.000.		Heterogeneous	3% Hair			
02	Plaster	Gray/White	5% Cellulose	85% Non-fibrous (other)	None Detected	
291302415-0002		Fibrous	5% Synthetic			
		Heterogeneous	5% Hair			
03	Plaster	Gray/White	8% Cellulose	82% Non-fibrous (other)	None Detected	
291302415-0003		Fibrous	5% Synthetic			
		Heterogeneous	5% Hair			
04	Mortar	Gray/White	8% Cellulose	82% Non-fibrous (other)	None Detected	
291302415-0004		Fibrous	5% Synthetic			
		Heterogeneous	5% Hair			
05	Mortar	Gray/White	8% Cellulose	82% Non-fibrous (other)	None Detected	
291302415-0005		Fibrous	5% Synthetic			
		Heterogeneous	5% Hair			
06	Mortar	Gray/White	5% Cellulose	85% Non-fibrous (other)	None Detected	
291302415-0006		Fibrous	5% Synthetic			
		Heterogeneous	5% Hair			

Analyst(s)

Billy Barnes (32) Essie Spencer (64) Essie Spencer, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Reporting limit is 1%

Samples analyzed by EMSL Analytical, Inc. Morrisville, NC NVLAP Lab Code 200671-0, VA 3333 000278, WVA LT000296



2500 Gateway Centre Blvd., Suite 600, Morrisville, NC 27560

Phone/Fax: (919) 465-3900 / (919) 465-3950

http://www.emsl.com raleighlab@emsl.com

EMSL Order: 291302415 CustomerID: ENSO62

CustomerPO: ProjectID:

Attn: Sonia Rogers

Environmental Solutions, LLC

PO Box 7010

Fax:

(406) 579-1441

Received:

Phone:

05/02/13 9:30 AM

Analysis Date: 5/7/2013

Collected:

Bozeman, MT 59771

Project: 13031-01, Taylor Hall

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

				Non-Asbe	<u>Asbestos</u>	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type
07	Concrete	Tan/Beige	10%	Cellulose	80% Non-fibrous (other)	None Detected
291302415-0007		Fibrous	5%	Synthetic		
20,002,00		Heterogeneous	5%	Hair		
08	Concrete	Tan/Beige	10%	Cellulose	80% Non-fibrous (other)	None Detected
291302415-0008		Fibrous	5%	Synthetic		
		Heterogeneous	5%	Hair		
09	Concrete	Tan/Beige	10%	Cellulose	80% Non-fibrous (other)	None Detected
291302415-0009		Fibrous	5%	Synthetic		
		Heterogeneous	5%	Hair		
10	Window Glazing	Tan/Beige	3%	Cellulose	95% Non-fibrous (other)	None Detected
291302415-0010		Fibrous	2%	Wollastonite		
		Homogeneous				
11	Window Glazing	Tan/Beige	2%	Wollastonite	96% Non-fibrous (other)	None Detected
291302415-0011		Fibrous	2%	Cellulose		
		Homogeneous				
12	Window Glazing	Tan/Beige	5%	Cellulose	93% Non-fibrous (other)	None Detected
291302415-0012		Fibrous	2%	Wollastonite		
		Homogeneous				
13-Rubber	Rubber Base w/	Black			100% Non-fibrous (other)	None Detected
291302415-0013	glue	Non-Fibrous Homogeneous				

Analyst(s)

Billy Barnes (32) Essie Spencer (64) Essie Spencer, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Reporting limit is 1%

Samples analyzed by EMSL Analytical, Inc. Morrisville, NC NVLAP Lab Code 200671-0, VA 3333 000278, WVA LT000296



2500 Gateway Centre Blvd., Suite 600, Morrisville, NC 27560

Phone/Fax: (919) 465-3900 / (919) 465-3950

http://www.emsl.com raleighlab@emsl.com

EMSL Order: 291302415 CustomerID: ENSO62

CustomerPO: ProjectID:

Attn: Sonia Rogers

Environmental Solutions, LLC

PO Box 7010

Phone: Fax:

(406) 579-1441

Received:

05/02/13 9:30 AM

Analysis Date: 5/7/2013

Collected:

Bozeman, MT 59771

Project: 13031-01, Taylor Hall

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

				Non-Ask	<u>pestos</u>	<u>Asbestos</u>	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type	
13-Glue	Rubber Base w/	Tan	25%	Cellulose	75% Non-fibrous (other)	None Detected	
291302415-0013A	glue	Fibrous Heterogeneous					
14-Rubber	Rubber Base w/	Black			100% Non-fibrous (other)	None Detected	
291302415-0014	glue	Non-Fibrous Homogeneous					
14-Glue	Rubber Base w/	Tan	15%	Cellulose	85% Non-fibrous (other)	None Detected	
291302415-0014A	glue	Fibrous Homogeneous					
15-Rubber	Rubber Base w/	Black			100% Non-fibrous (other)	None Detected	
291302415-0015	glue	Non-Fibrous Homogeneous					
15-Glue	Rubber Base w/	Tan	15%	Cellulose	85% Non-fibrous (other)	None Detected	
291302415-0015A	glue	Fibrous Homogeneous					
16	Mastic	Brown/Black	5%	Cellulose	93% Non-fibrous (other)	None Detected	
291302415-0016		Fibrous Heterogeneous	2%	Synthetic			
17	Mastic	Brown/Black	5%	Cellulose	93% Non-fibrous (other)	None Detected	
291302415-0017		Fibrous Heterogeneous	2%	Synthetic			
18	Mastic	Brown/Black	8%	Cellulose	89% Non-fibrous (other)	None Detected	
291302415-0018		Fibrous Heterogeneous	3%	Synthetic			

Analyst(s)

Billy Barnes (32) Essie Spencer (64) Essie Spencer, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Reporting limit is 1%

Samples analyzed by EMSL Analytical, Inc. Morrisville, NC NVLAP Lab Code 200671-0, VA 3333 000278, WVA LT000296



2500 Gateway Centre Blvd., Suite 600, Morrisville, NC 27560

Phone/Fax: (919) 465-3900 / (919) 465-3950

http://www.emsl.com raleighlab@emsl.com

EMSL Order: 291302415 CustomerID: ENSO62

CustomerPO: ProjectID:

Attn: Sonia Rogers

Environmental Solutions, LLC

PO Box 7010

Project: 13031-01, Taylor Hall

Phone:

(406) 579-1441

Fax:

Received:

05/02/13 9:30 AM

Analysis Date: 5/7/2013

Collected:

Bozeman, MT 59771

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

				Non-Asbe	<u>Asbestos</u>	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type
19	Paint	White	2%	Wollastonite	96% Non-fibrous (other)	None Detected
291302415-0019		Fibrous Heterogeneous	2%	Cellulose		
20	Paint	White/Beige	2%	Wollastonite	96% Non-fibrous (other)	None Detected
291302415-0020		Fibrous Homogeneous	2%	Cellulose		
21	Paint	White/Beige	2%	Cellulose	96% Non-fibrous (other)	None Detected
291302415-0021		Fibrous Heterogeneous	2%	Wollastonite		
22-Drywall	Drywall/Mud/Textu	Brown/White	20%	Cellulose	80% Non-fibrous (other)	None Detected
291302415-0022	re	Fibrous Heterogeneous				
22-Mud	Drywall/Mud/Textu	Beige	5%	Cellulose	95% Non-fibrous (other)	None Detected
291302415-0022A	re	Fibrous Homogeneous				
22-Texture	Drywall/Mud/Textu	Beige	2%	Wollastonite	98% Non-fibrous (other)	None Detected
291302415-0022B	re	Fibrous Homogeneous				
23-Drywall	Drywall/Mud/Textu	Brown/White	25%	Cellulose	75% Non-fibrous (other)	None Detected
291302415-0023	re	Fibrous Heterogeneous				
23-Mud	Drywall/Mud/Textu	Beige	3%	Cellulose	97% Non-fibrous (other)	None Detected
291302415-0023A	re	Fibrous Homogeneous				

Analyst(s)

Billy Barnes (32) Essie Spencer (64) Essie Spencer, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Reporting limit is 1%

Samples analyzed by EMSL Analytical, Inc. Morrisville, NC NVLAP Lab Code 200671-0, VA 3333 000278, WVA LT000296



2500 Gateway Centre Blvd., Suite 600, Morrisville, NC 27560

Phone/Fax: (919) 465-3900 / (919) 465-3950

http://www.emsl.com raleighlab@emsl.com

EMSL Order: CustomerID:

291302415

ENSO62

CustomerPO: ProjectID:

Attn: Sonia Rogers

Environmental Solutions, LLC

PO Box 7010

Phone: Fax:

(406) 579-1441

Received:

05/02/13 9:30 AM

Analysis Date: 5/7/2013

Collected:

Bozeman, MT 59771

Project: 13031-01, Taylor Hall

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

				Non-Asbe	<u>estos</u>	<u>Asbestos</u>
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type
23-Texture	Drywall/Mud/Textu re	ū	2%	Wollastonite	98% Non-fibrous (other)	None Detected
291302415-0023B	16	Fibrous Homogeneous				
24-Drywall	Drywall/Mud/Textu		25%	Cellulose	75% Non-fibrous (other)	None Detected
291302415-0024	re	Fibrous Heterogeneous				
24-Mud	Drywall/Mud/Textu	ū	2%	Cellulose	98% Non-fibrous (other)	None Detected
291302415-0024A	re	Fibrous Homogeneous				
24-Texture	Drywall/Mud/Textu	ū	5%	Cellulose	95% Non-fibrous (other)	None Detected
291302415-0024B	re	Fibrous Homogeneous				
25	12x12 Floor Tile	Gray	2%	Cellulose	98% Non-fibrous (other)	None Detected
291302415-0025	w/ Glue	Fibrous Homogeneous				
			No glue pr	esent.		
26	12x12 Floor Tile	Gray	5%	Cellulose	95% Non-fibrous (other)	None Detected
291302415-0026	w/ Glue	Fibrous Homogeneous				
			No glue pr	esent.		
27	12x12 Floor Tile	Gray	2%	Cellulose	98% Non-fibrous (other)	None Detected
291302415-0027	w/ Glue	Fibrous Homogeneous				
			No glue pr	esent.		

Analyst(s)

Billy Barnes (32) Essie Spencer (64) Essie Spencer, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Reporting limit is 1%

Samples analyzed by EMSL Analytical, Inc. Morrisville, NC NVLAP Lab Code 200671-0, VA 3333 000278, WVA LT000296



2500 Gateway Centre Blvd., Suite 600, Morrisville, NC 27560

Phone/Fax: (919) 465-3900 / (919) 465-3950

http://www.emsl.com raleighlab@emsl.com

EMSL Order: 291302415 CustomerID: ENSO62

CustomerPO: ProjectID:

Attn: Sonia Rogers

Environmental Solutions, LLC

PO Box 7010

Phone: Fax:

(406) 579-1441

Received:

05/02/13 9:30 AM

Analysis Date: 5/7/2013

Collected:

Bozeman, MT 59771

Project: 13031-01, Taylor Hall

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

				Non-Ask	<u>pestos</u>	<u>Asbestos</u>	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type	
28	CMU	Gray/White	5%	Cellulose	93% Non-fibrous (other)	None Detected	
291302415-0028		Fibrous Heterogeneous	2%	Synthetic			
29	CMU	Gray/White	2%	Cellulose	96% Non-fibrous (other)	None Detected	
291302415-0029		Fibrous Heterogeneous	2%	Synthetic			
30	CMU	Gray/White	5%	Cellulose	95% Non-fibrous (other)	None Detected	
291302415-0030		Fibrous Homogeneous					
31	CMU Mortar	Gray/White	5%	Cellulose	90% Non-fibrous (other)	None Detected	
291302415-0031		Fibrous Heterogeneous	5%	Synthetic			
32	CMU Mortar	Gray/White	5%	Cellulose	92% Non-fibrous (other)	None Detected	
291302415-0032		Fibrous Heterogeneous	3%	Synthetic			
33	CMU Mortar	Gray/White	5%	Cellulose	92% Non-fibrous (other)	None Detected	
291302415-0033		Fibrous Heterogeneous	3%	Synthetic			
34-Floor Tile	12x12 Floor Tile	Tan/Beige	5%	Cellulose	93% Non-fibrous (other)	2% Chrysotile	
291302415-0034	w/ Mastic	Fibrous Homogeneous					
34-Mastic	12x12 Floor Tile	Tan	5%	Cellulose	95% Non-fibrous (other)	None Detected	
291302415-0034A	w/ Mastic	Fibrous Homogeneous					

Analyst(s)

Billy Barnes (32) Essie Spencer (64) Essie Spencer, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Reporting limit is 1%

Samples analyzed by EMSL Analytical, Inc. Morrisville, NC NVLAP Lab Code 200671-0, VA 3333 000278, WVA LT000296



2500 Gateway Centre Blvd., Suite 600, Morrisville, NC 27560

(919) 465-3900 / (919) 465-3950

raleighlab@emsl.com http://www.emsl.com

EMSL Order: 291302415 CustomerID:

ProjectID:

ENSO62

CustomerPO:

Attn: Sonia Rogers

Environmental Solutions, LLC

PO Box 7010

Phone:

(406) 579-1441

Fax:

Received:

05/02/13 9:30 AM

Analysis Date: 5/7/2013

Collected:

Bozeman, MT 59771

Project: 13031-01, Taylor Hall

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

				Non-Asl	<u>Asbestos</u>		
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	%	Type
35-Floor Tile	12x12 Floor Tile	Tan	3%	Cellulose	95% Non-fibrous (other)	2%	Chrysotile
291302415-0035	w/ Mastic	Fibrous Homogeneous					
35-Mastic	12x12 Floor Tile	Tan	5%	Cellulose	95% Non-fibrous (other)		None Detected
291302415-0035A	w/ Mastic	Fibrous Homogeneous					
36-Floor Tile	12x12 Floor Tile	Beige	2%	Cellulose	96% Non-fibrous (other)	2%	Chrysotile
291302415-0036	w/ Mastic	Fibrous Homogeneous					
36-Mastic	12x12 Floor Tile	Tan	8%	Cellulose	92% Non-fibrous (other)		None Detected
291302415-0036A	w/ Mastic	Fibrous Homogeneous					
37	Rubber Base	Black			100% Non-fibrous (other)		None Detected
291302415-0037		Non-Fibrous Homogeneous					
38	Rubber Base	Black			100% Non-fibrous (other)		None Detected
291302415-0038		Non-Fibrous Homogeneous					
39	Rubber Base	Black			100% Non-fibrous (other)		None Detected
291302415-0039		Non-Fibrous Homogeneous					
40	2x4 Ceiling Tiles	Tan/White	10%	Cellulose	10% Perlite		None Detected
291302415-0040		Fibrous Homogeneous	20%	Min. Wool	60% Non-fibrous (other)		

Analyst(s)

Billy Barnes (32) Essie Spencer (64) Essie Spencer, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Reporting limit

Samples analyzed by EMSL Analytical, Inc. Morrisville, NC NVLAP Lab Code 200671-0, VA 3333 000278, WVA LT000296



2500 Gateway Centre Blvd., Suite 600, Morrisville, NC 27560

Phone/Fax: (919) 465-3900 / (919) 465-3950

http://www.emsl.com raleighlab@emsl.com

EMSL Order: 291302415 CustomerID: ENSO62

CustomerPO: ProjectID:

Attn: Sonia Rogers

Environmental Solutions, LLC

PO Box 7010

Phone: Fax:

(406) 579-1441

Received:

05/02/13 9:30 AM

Analysis Date: 5/7/2013

Collected:

Bozeman, MT 59771

Project: 13031-01, Taylor Hall

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

				Non-Ask	<u>estos</u>	<u>Asbestos</u>
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type
41	2x4 Ceiling Tiles	White/Beige	20%	Cellulose	10% Perlite	None Detected
291302415-0041		Fibrous Heterogeneous	15%	Min. Wool	55% Non-fibrous (other)	
42	2x4 Ceiling Tiles	White/Beige	20%	Cellulose	20% Perlite	None Detected
291302415-0042		Fibrous Homogeneous	20%	Min. Wool	40% Non-fibrous (other)	
43	12x12 Ceiling Tile	Tan	85%	Cellulose	15% Non-fibrous (other)	None Detected
291302415-0043		Fibrous Heterogeneous				
44	12x12 Ceiling Tile	Tan	85%	Cellulose	15% Non-fibrous (other)	None Detected
291302415-0044		Fibrous Heterogeneous				
45	12x12 Ceiling Tile	Tan/White	80%	Cellulose	20% Non-fibrous (other)	None Detected
291302415-0045		Fibrous Heterogeneous				
46	12x12 Ceiling Tile	Brown	5%	Cellulose	95% Non-fibrous (other)	None Detected
291302415-0046	Glue	Fibrous Heterogeneous				
47	12x12 Ceiling Tile	Brown	5%	Cellulose	95% Non-fibrous (other)	None Detected
291302415-0047	Glue	Fibrous Homogeneous				
48	12x12 Ceiling Tile	Brown	5%	Cellulose	95% Non-fibrous (other)	None Detected
291302415-0048	Glue	Fibrous Homogeneous				

Analyst(s)

Billy Barnes (32) Essie Spencer (64) Essie Spencer, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Reporting limit is 1%

Samples analyzed by EMSL Analytical, Inc. Morrisville, NC NVLAP Lab Code 200671-0, VA 3333 000278, WVA LT000296



2500 Gateway Centre Blvd., Suite 600, Morrisville, NC 27560

(919) 465-3900 / (919) 465-3950

raleighlab@emsl.com http://www.emsl.com

EMSL Order: 291302415 CustomerID: ENSO62

CustomerPO: ProjectID:

Attn: Sonia Rogers

Environmental Solutions, LLC

PO Box 7010

Phone: Fax:

(406) 579-1441

Received:

05/02/13 9:30 AM

Analysis Date: 5/7/2013

Collected:

Bozeman, MT 59771

Project: 13031-01, Taylor Hall

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

				Non-As	<u>Asbestos</u>		
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	%	Type
49-Linoleum	Linoleum w/ Glue	Tan/Beige	20%	Cellulose	55% Non-fibrous (other)	25%	Chrysotile
291302415-0049		Fibrous Heterogeneous					
49-Glue	Linoleum w/ Glue	Tan	5%	Cellulose	95% Non-fibrous (other)	<1%	Chrysotile
291302415-0049A		Fibrous Heterogeneous					
			Possible c	ontainmination from b	acking.		
50-Linoleum	Linoleum w/ Glue	Tan/Beige	20%	Cellulose	55% Non-fibrous (other)	25%	Chrysotile
291302415-0050		Fibrous Heterogeneous					
50-Glue	Linoleum w/ Glue	Tan	5%	Cellulose	95% Non-fibrous (other)	<1%	Chrysotile
291302415-0050A		Fibrous Heterogeneous					
			Possible c	ontainmination from b	acking.		
51-Linoleum	Linoleum w/ Glue	Tan/Beige	20%	Cellulose	55% Non-fibrous (other)	25%	Chrysotile
291302415-0051		Fibrous Heterogeneous					
51-Glue	Linoleum w/ Glue	Tan	5%	Cellulose	95% Non-fibrous (other)	<1%	Chrysotile
291302415-0051A		Fibrous Homogeneous					
			Possible c	ontainmination from b	acking.		
52-Floor Tile	9x9 Floor Tile w/	Green	5%	Cellulose	93% Non-fibrous (other)	2%	Chrysotile
291302415-0052	Glue	Fibrous Homogeneous					

Analyst(s)

Billy Barnes (32) Essie Spencer (64) Essie Spencer, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Reporting limit

Samples analyzed by EMSL Analytical, Inc. Morrisville, NC NVLAP Lab Code 200671-0, VA 3333 000278, WVA LT000296



2500 Gateway Centre Blvd., Suite 600, Morrisville, NC 27560

Phone/Fax: (919) 465-3900 / (919) 465-3950

http://www.emsl.com raleighlab@emsl.com

EMSL Order: 291302415 CustomerID: ENSO62

CustomerPO: ProjectID:

Attn: Sonia Rogers

Environmental Solutions, LLC

PO Box 7010

Phone: Fax: (406) 579-1441

Fax:

Received:

05/02/13 9:30 AM

Analysis Date: 5/7/2013

Collected:

Bozeman, MT 59771

Project: 13031-01, Taylor Hall

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

		Non-Asbestos					<u>Asbestos</u>	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	%	Туре	
52-Mastic	9x9 Floor Tile w/	Brown/Black	15%	Cellulose	85% Non-fibrous (other)		None Detected	
291302415-0052A	Glue	Fibrous Homogeneous						
53-Floor Tile	9x9 Floor Tile w/	Green	2%	Wollastonite	94% Non-fibrous (other)	2%	Chrysotile	
291302415-0053	Glue	Fibrous Homogeneous	2%	Cellulose				
53-Mastic	9x9 Floor Tile w/	Brown/Black	15%	Cellulose	85% Non-fibrous (other)		None Detected	
291302415-0053A	Glue	Fibrous Heterogeneous						
54-Floor Tile	9x9 Floor Tile w/	Green	5%	Cellulose	93% Non-fibrous (other)	2%	Chrysotile	
291302415-0054	Glue	Fibrous Homogeneous						
54-Mastic	9x9 Floor Tile w/	Brown/Black	15%	Cellulose	85% Non-fibrous (other)		None Detected	
291302415-0054A	Glue	Fibrous Heterogeneous						
55-Drywall	Drywall/Mud/Textu	Brown/White	15%	Cellulose	82% Non-fibrous (other)		None Detected	
291302415-0055	re	Fibrous Heterogeneous	3%	Glass				
55-Joint Compound	•		5%	Cellulose	90% Non-fibrous (other)	5%	Chrysotile	
291302415-0055A	re	Non-Fibrous Homogeneous	<1%	Wollastonite				
55-Composite	Drywall/Mud/Textu	0	15%	Cellulose	82% Non-fibrous (other)	<1%	Chrysotile	
	re	e Fibrous	3%	Glass				
291302415-0055B		Heterogeneous	<1%	Wollastonite				

Analyst(s)

Billy Barnes (32) Essie Spencer (64) Essie Spencer, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Reporting limit is 1%

Samples analyzed by EMSL Analytical, Inc. Morrisville, NC NVLAP Lab Code 200671-0, VA 3333 000278, WVA LT000296



2500 Gateway Centre Blvd., Suite 600, Morrisville, NC 27560

Phone/Fax: (919) 465-3900 / (919) 465-3950

http://www.emsl.com raleighlab@emsl.com

EMSL Order: 291302415 CustomerID: ENSO62

CustomerPO: ProjectID:

Attn: Sonia Rogers

Environmental Solutions, LLC

PO Box 7010

Bozeman, MT 59771

Project: 13031-01, Taylor Hall

Phone: (406) 579-1441

Fax:

Received: 05/02/13 9:30 AM

Analysis Date: 5/7/2013

Collected:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

			Non-Asbestos			<u>Asbestos</u>	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	%	Type
56-Drywall 291302415-0056	Drywall/Mud/Textu re	Brown/White Fibrous Heterogeneous	15% 3%		82% Non-fibrous (other)		None Detected
56-Joint Compound 291302415-0056A	Drywall/Mud/Textu re	Beige Fibrous Homogeneous	2% 5%	Wollastonite Cellulose	88% Non-fibrous (other)	5%	Chrysotile
56-Composite 291302415-0056B	Drywall/Mud/Textu re	Brown/White/Beig e Fibrous Heterogeneous	15% 2% <1%	Cellulose Glass Wollastonite	83% Non-fibrous (other)	<1%	Chrysotile
57-Drywall 291302415-0057	Drywall/Mud/Textu re	Brown/White Fibrous Heterogeneous	15% 3%	Cellulose Glass	82% Non-fibrous (other)		None Detected
57-Joint Compound	Drywall/Mud/Textu re	White Fibrous Heterogeneous	5% 2%	Cellulose Wollastonite	88% Non-fibrous (other)	5%	Chrysotile
57-Composite 291302415-0057B	Drywall/Mud/Textu re	Brown/White/Beig e Fibrous Heterogeneous	15% 2% <1%	Cellulose Glass Wollastonite	83% Non-fibrous (other)	<1%	Chrysotile
58 291302415-0058	Wall Tile Glue	Brown/Tan Fibrous Heterogeneous	2%	Cellulose	98% Non-fibrous (other)		None Detected

Analyst(s)

Billy Barnes (32) Essie Spencer (64) Essie Spencer, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Reporting limit is 1%

Samples analyzed by EMSL Analytical, Inc. Morrisville, NC NVLAP Lab Code 200671-0, VA 3333 000278, WVA LT000296



2500 Gateway Centre Blvd., Suite 600, Morrisville, NC 27560

Phone/Fax: (919) 465-3900 / (919) 465-3950

http://www.emsl.com raleighlab@emsl.com

EMSL Order: 291302415 CustomerID: ENSO62

CustomerPO: ProjectID:

Attn: Sonia Rogers

Environmental Solutions, LLC

PO Box 7010

Phone: Fax: (406) 579-1441

гах.

Received:

05/02/13 9:30 AM

Analysis Date: 5/7/2013

Collected:

Bozeman, MT 59771

Project: 13031-01, Taylor Hall

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

				<u>pestos</u>	<u>Asbestos</u>	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type
59	Wall Tile Glue	Brown/Tan	2%	Cellulose	98% Non-fibrous (other)	None Detected
291302415-0059		Fibrous Heterogeneous				
60	Wall Tile Glue	Brown/Tan	3%	Cellulose	97% Non-fibrous (other)	None Detected
291302415-0060		Fibrous Heterogeneous				
61	Brick	Tan/White	3%	Cellulose	97% Non-fibrous (other)	None Detected
291302415-0061		Fibrous Heterogeneous				
62	Brick	Brown/Tan	3%	Cellulose	97% Non-fibrous (other)	None Detected
291302415-0062		Fibrous Heterogeneous				
63	Brick	Brown/Tan	5%	Cellulose	95% Non-fibrous (other)	None Detected
291302415-0063		Fibrous Heterogeneous				
64	Brick Mortar	White/Beige	8%	Cellulose	92% Non-fibrous (other)	None Detected
291302415-0064		Fibrous Heterogeneous				
65	Brick Mortar	White/Beige	5%	Cellulose	95% Non-fibrous (other)	None Detected
291302415-0065		Fibrous Heterogeneous				
66	Brick Mortar	White/Beige	5%	Cellulose	95% Non-fibrous (other)	None Detected
291302415-0066		Fibrous Heterogeneous				

Analyst(s)

Billy Barnes (32) Essie Spencer (64) Essie Spencer, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Reporting limit is 1%

Samples analyzed by EMSL Analytical, Inc. Morrisville, NC NVLAP Lab Code 200671-0, VA 3333 000278, WVA LT000296



2500 Gateway Centre Blvd., Suite 600, Morrisville, NC 27560

(919) 465-3900 / (919) 465-3950

raleighlab@emsl.com http://www.emsl.com

EMSL Order: CustomerID:

291302415

ENSO62

CustomerPO: ProjectID:

Sonia Rogers

Environmental Solutions, LLC

PO Box 7010

Phone: Fax:

(406) 579-1441

Received:

05/02/13 9:30 AM

Analysis Date: 5/7/2013

Collected:

Bozeman, MT 59771

Project: 13031-01, Taylor Hall

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

		Non-Asbestos					<u>Asbestos</u>		
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	%	Туре		
67 291302415-0067	Exterior Caulk	Tan/Beige Fibrous Heterogeneous	8% 2%	Cellulose Wollastonite	87% Non-fibrous (other)	3%	Chrysotile		
68 291302415-0068	Exterior Caulk	Gray/Beige Fibrous Heterogeneous	10% 2%	Cellulose Wollastonite	86% Non-fibrous (other)	2%	Chrysotile		
69 291302415-0069	Exterior Caulk	Tan/Beige Fibrous Heterogeneous	5% 2%	Cellulose Wollastonite	91% Non-fibrous (other)	2%	Chrysotile		
70 291302415-0070	Roofing Materials	Brown/Black Fibrous Heterogeneous	10%	Cellulose	88% Non-fibrous (other)	2%	Chrysotile		
71 291302415-0071	Roofing Materials	Brown/Black Fibrous Heterogeneous	30%	Cellulose	62% Non-fibrous (other)	8%	Chrysotile		
72 291302415-0072	Roofing Materials	Brown/Black Fibrous Heterogeneous	15%	Cellulose	77% Non-fibrous (other)	8%	Chrysotile		

Analyst(s)

Billy Barnes (32) Essie Spencer (64) Essie Spencer, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Reporting limit

Samples analyzed by EMSL Analytical, Inc. Morrisville, NC NVLAP Lab Code 200671-0, VA 3333 000278, WVA LT000296



2500 Gateway Centre Blvd., Suite 600, Morrisville, NC 27560

Phone/Fax: (919) 465-3900 / (919) 465-3950

http://www.EMSL.com raleighlab@emsl.com CustomerID: CustomerPO: ProjectID:

EMSL Order:

291307927

ENSO62

Sonia Rogers **Environmental Solutions, LLC**

Phone: Fax:

(406) 579-1441

Received:

12/19/13 10:15 AM

Analysis Date: 12/19/2013

Collected:

Bozeman, MT 59771

Project: MSU Taylor

PO Box 7010

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using **Polarized Light Microscopy**

			Non-Asbestos					
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type			
01	Tar Paper	Brown/Black	85% Cellulose	15% Non-fibrous (other)	None Detected			
291307927-0001		Fibrous Homogeneous						
02	Tar Paper	Brown/Black	85% Cellulose	15% Non-fibrous (other)	None Detected			
291307927-0002		Fibrous Homogeneous						
03	Tar Paper	Brown/Black	85% Cellulose	15% Non-fibrous (other)	None Detected			
291307927-0003		Fibrous Homogeneous						

Analyst(s)

Essie Spencer (3)

Essie Spencer, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Morrisville, NC NVLAP Lab Code 200671-0, VA 3333 000278, WVA LT000296

Initial report from 12/19/2013 13:37:03

APPENDIX C

CHAIN OF CUSTODY DOCUMENTS

Environmental Solutions, LLC

13031-01, Taylor Hall

5/2/2013 9:30 PLM

TAT: 96 Hour

Bulk

Order ID: 291302415 No Samples: 72

Due: 05/08 9:30 AM

Raleigh, NC 2500 Gateway Centre Blvd. Suite 600 Morrisville, NC 27560 PHONE: 919-465-3900

Company: Environmental Solu	itions LLC		F	MSL-Bill to: ✓ Same Different	FAX: 919-465-395
Street: PO Box 7010	ations LEO		If Bill t	o is Different note instructions in Commen	ts**
City/State/Zip: Bozeman, MT	59771-7010	***************************************	Third Party Bill	ling requires written authorization from	m third party
Report To (Name): Sonia Rog	ASSESSMENT OF THE PROPERTY OF		Fax: 406-587-0193		
Telephone: 406-579-1441			Email Address: srogers@esm	nontana com	
Project Name/Number:	13031-01	Taylor	Ha /	ionana.com	
Please Provide Results: Ema	il Purchase Order:	ragio	State Samples Taken: MT		
	Turn	around Time (TAT)	Options' - Please Che		
	Hour 24 Hour	☐ 48 Hour	72 Hour (💢 :	95 Hour 1 Week	☐ 2 Week
*For TEM Air 3 hours/6 h	ours, please call ahead to sch	edule, 'There is a premiu	m charge for 3 Hour TEM AH	ERA of EPA Level II TAT. Y	ou will be asked to sign
an authorization fo	orm for this service. Analysis				cal Price Guide.
PCM - Air			5hr TAT (AHERA only)	TEM- Dust	
☐ NIOSH 7400		AHERA 40 CF	R, Part 763	☐ Microvac - ASTM □	5755
w/ OSHA 8hr. TW/		☐ NIOSH 7402		☐ Wipe - ASTM D648	30
PLM - Bulk (reporting	g limit)	☐ EPA Level II		☐ Carpet Sonication	(EPA 600/J-93/167)
PLM EPA 600/R-93	3/116 (<1%)	☐ ISO 10312		Soil/Rock/Vermiculite	
PLM EPA NOB (<1		TEM - Bulk		PLM CARB 435 - A	
Point Count	,	T TEM EPA NOB		PLM CARB 435 - B	
400 (<0.25%) 1	000 (<0.1%)	NYS NOB 198.4	(non friable NV)	The Committee of the Co	
Point Count w/Gravime	100	☐ Chatfield SOP	(non-mable-NT)	TEM CARB 435 - B	
400 (<0.25%) 1				TEM CARB 435 - C	
			ysis-EPA 600 sec. 2.5	EPA Protocol (Sem	10 to
NYS 198.1 (friable	5	TEM - Water: EPA		☐ EPA Protocol (Qua	ntitative)
☐ NYS 198.6 NOB (r	non-friable-NY)		Waste Drinking	Other:	
■ NIOSH 9002 (<1%			Waste Drinking		
	Check For P	ositive Stop - Cle	arly Identify Homogo	enous Group	
1015 NY 607401					-to figure water was a second
Samplers Name:			Samplers Signature:		
Sample #				Volume/Area (Air)	Date/Time
Sample #		Sample Description		HA# (Bulk)	Sampled
				1	
	40	A 11 1	/	The state of the s	
	* Dec	Attache			
	*				
			THE RESERVE OF THE PARTY OF THE		
Client Sample # (s):	\circ	•		Total # of Samples:	72
Relinquished (Client)	: Soma D	CLLYS Date:	5-1-13	Time:	1:00pm
Received (Lab):		Date:	5/2	Time:	9/5/)
Comments/Special Instruction	ns:				· - U
			EFE 8	766 8750 093	ν.
			0, 0	· 40 0 / 30 0/3	

CHAIN OF CUSTODY For Environmental Solutions LLC

Date Shipped: 5-1-13	Number of Samples:
Project ID: 3031-01 To	ylor Hall
Shipped Via: Fed-Ex Standard	Fed-Ex AM Delivery Fed-Ex Saturday
US Mail	•

Sample ID	Sample Description	Quantity
01-02-03	Plaster	3
04-05-06	Mortar	3
07-08-09	Concrete	3
10-11-12	Window Glazing	3
13-14-15	Rubber Base w/Glue	3
16-17-18	Mastic	3
19-20-21	Paint	3
22-23-24	Drywall / Mud / Texture	3
25-26-27	12x12 Floor Tile w/Glue	3
28-29-30	CMU	3
31-32-33	CMU Mortar	3
34-35-36	12x12 Floor Tile w/Mastic	3
37-38-39	Rubber Base	3
40-41-42	2x4 Ceiling Tiles	3
43-44-45	12x12 Ceiling Tiles	3
46-47-48	12x12 Ceiling Tile Glue	3
49-50-51	Linoleum w/Glue	3
52-53-54	9x9 Floor Tile w/Mastic	3
55-56-57	Drywall / Mud / Texture	3
58-59-60	Wall Tile Glue	3
61-62-63	Brick	3
64-65-66	Brick Mortar	3
67-68-69	Exterior Caulk	3
70-71-72	Roofing Materials	3
COCO		
Environmental Solu 13031-01, Taylor Hall	No Samples: 72	
5/2/2013 9:30 PLM	Bulk Fax: 05/08 9:30 AM	

J 5/2 9130

Environmental Solutions, LLC

MSU Taylor

12/19/2013 10:1 PLM

Controlled Document - Asbestos Lab Services COC - A1.0 - 11/23/2009

TAT: 6 Hour Bulk Order ID: 291307927 No Samples: 3 **Due:** 12/19 4:15 PM


Fax:

Raleigh, NC 2500 Gateway Centre Blvd. Suite 600 Morrisville, NC 27560 PHONE: 919-465-3900

Company: Environmental Sale	diana I I C		-		FAX: 919-465-395
Company: Environmental Solutions LLC Street: PO Box 7010			EMSL-Bill to: Same Offerent If Bill to is Different note instructions in Comments**		
City/State/Zip: Bozeman, MT 59771-7010			Third Party Billing requires written authorization from third party		
Report To (Name): Sonia Rog					
Telephone: 406-579-1441	ers		Fax: 406-587-0193		
Project Name/Number:	MS/1-Tour		Email Address: srogers@esm	nontana.com	
Please Provide Results: Ema		or	State Semules Taken MT		
1		paround Time (TAT)	State Samples Taken: MT		
*For TEM Air 3 hours/6 h an authorization is	Hour 24 Hour	hedule.*There is a premium s completed in accordance	72 Hour 9 ! charge for 3 Hour TEM AH with EMSL's Terms and Co	96 Hour 1 Week #ERA or EPA Level II TAT. Younditions located in the Analytic	2 Week u will be asked to sign al Price Guide.
PCM - Air		TEM - Air 4-4.5hr TAT (AHERA only)		TEM- Dust	
☐ NIOSH 7400		AHERA 40 CFR, Part 763		☐ Microvac - ASTM D 5755	
w/ OSHA 8hr. TWA		☐ NIOSH 7402		☐ Wipe - ASTM D6480	
PLM - Bulk (reporting limit)		☐ EPA Level II		☐ Carpet Sonication (EPA 600/J-93/167)	
PLM EPA 600/R-93/116 (<1%)		☐ ISO 10312			
				Soil/Rock/Vermiculite	
PLM EPA NOB (<1%)		TEM - Bulk		☐ PLM CARB 435 - A (0.25% sensitivity) ☐ PLM CARB 435 - B (0.1% sensitivity)	
Point Count		TEM EPA NOB			
400 (<0.25%) 🔲 1		NYS NOB 198.4 (non-friable-NY)		☐ TEM CARB 435 - B (0.1% sensitivity) ☐ TEM CARB 435 - C (0.01% sensitivity) ☐ EPA Protocol (Semi-Quantitative)	
Point Count w/Gravime		☐ Chatfield SOP			
400 (<0.25%) 🔲 10	000 (<0.1%)	☐ TEM Mass Analysis-EPA 600 sec. 2.5			
☐ NYS 198.1 (friable in NY)		TEM - Water: EPA 100.2		☐ EPA Protocol (Quantitative)	
☐ NYS 198.6 NOB (r	non-friable-NY)	Fibers >10µm ☐ Waste ☐ Drinking		Other:	
☐ NIOSH 9002 (<1%		All Fiber Sizes V			
□ 14100113002 C176			rly Identify Homoge		
	1		in a second and the second	cilous dioup	
Samplers Name:	Y		Samplers Signature:		
Samplers Name: Sample #	V	Sample Description		Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
	Tar pa			Volume/Area (Air)	
	Tar po			Volume/Area (Air)	
	Tar po			Volume/Area (Air)	
	Tar po			Volume/Area (Air)	
	Tarpo			Volume/Area (Air)	
	Tar po			Volume/Area (Air)	
	Tarpo			Volume/Area (Air)	
	Tarpo			Volume/Area (Air)	
	Tarpo		Samplers Signature:	Volume/Area (Air)	
Sample # 01-02-03	Tarpo		Samplers Signature:	Volume/Area (Air) HA # (Bulk)	
Sample # OI-O2-O3 Client Sample # (s): Relinquished (Client). Received (Lab):	Sma Ro	Sample Description	Samplers Signature:	Volume/Area (Air) HA # (Bulk) Total # of Samples:	
Sample # O1-O2-O3 Client Sample # (s): Relinquished (Client)	Sma Ro	Sample Description	Samplers Signature:	Volume/Area (Air) HA # (Bulk) Total # of Samples:	Sampled 3 //30

APPENDIX D


FLOOR PLANS








INDEX#








INDEX#

BUILDING # 108





Jan 24, 2012 - 9:13am - 108_A3.dvg H:\Taylor\Building Plan - Book Copy\





APPENDIX E

ABBREVIATIONS

A/C asbestos/cement

ACM asbestos-containing material

AHERA Asbestos Hazard Emergency Response Act of 1986

ANSI American National Standards Institute

ASTM American Society for Testing and Materials

BID background information document

CAA Clean Air Act

CPSC Consumer Products Safety Commission

DOT Department of Transportation

EPA Environmental Protection Agency

ID identification

LEV local exhaust ventilation

NADC National Association of Demolition Contractors

NARS National Asbestos Registry System

NESHAP National Emission Standards for Hazardous Air Pollutants

NIOSH National Institute for Occupational Safety and Health

OAQPS Office of Air Quality Planning and Standards

OSHA Occupational Safety and Health Administration

OSW Office of Solid Waste

PEL permissible exposure limit

PLM polarized light microscopy

RCRA Resource Conservation and Recovery Act

SARA Superfund Amendments and Reauthorization Act of 1986

TEM transmission electron microscopy

TSCA Toxic Substances Control Act